

土 質 柱 状 図 (No. 1)

調查名 千葉市宮住宅天台団地地質調査業務委託

調査地 千葉市稲毛区天台1丁目6番

調査年月日平成9年7月17日～9年7月19日

標 高 KBM -0.37 m

孔内水位 GL - 4.60 m

技術者

標 尺 m	標 高 m	深 度 m	層 厚 m	柱 状 図	色 調	土 質 名	観 察	原 位 置 試 験 深 度 m	標 準 貫 入 試 験										試 料		標 尺 m	
									深 度 m	N 値 回/cm	10cm 毎の 打 撃 回 数			N 値					採取 方法	採取 深度 m		
											10 cm	20 cm	30 cm	10	20	30	40	50				
1	-0.67	0.30	0.30		黒灰	表 土	有機質ローム主体。 粒径は均一。 含水量中位。 スコリア混入。															1
2								2.15	2		1	1										2
3								2.45	30													3
4	-4.27	3.90	3.60		茶褐	ロ ー ム		3.15	4	1	1	2										4
5								3.47	32			12										5
6								4.15	30			30										6
7	-6.07	5.70	1.80		乳黄灰	凝灰質粘土	色調混色。 酸化物・炭化物混入。 5.00m付近黄褐色の粘 土斑状に混入。 含水量中位。		4.45	30												7
8								5.15	30	1	1	1										8
9	-7.27	6.90	1.20		黄褐灰	砂質粘土	色調混色。 酸化物・炭化物混入。 含水量中位。 6.40m付近砂多量混入。		5.45	14	3	5	6									9
10								6.15	30													10
11	-9.37	9.00	2.10		暗黄灰	細 砂	7.00m付近より10cm 位固結した黒灰色の砂挟む。 含水量中位。 鉄分縞状に挟む。		6.45	48	13	15	20									11
12								7.15	30													12
13								7.45	32	8	10	14										13
14								8.15	30													14
15								8.45	34	10	11	13										15
16								9.15	30													16
17								9.45	38	11	13	14										17
18								10.15	30													18
19	-19.37	19.00	10.00		黄灰	細 砂	9.10m付近褐色の砂挟む。 含水量少ない。 10.20m付近褐色の砂挟む。 14.20m付近粘土薄く挟む。 炭化物少量混入。		10.45	35	11	11	13									19
20								11.15	30													20
21								11.45	60	15	24	21										21
22								12.15	27													22
23								12.42	34	10	11	13										23
24								13.15	30													24
25								13.45	38	8	13	17										25
26								14.15	30													26
27								14.45	52	13	14	25										27
28								15.15	32	8	11	13										28
29								15.45	30													29
30								16.15	32													30
31								16.45	43	10	14	19										31
32								17.15	60	15	25	20										32
33								17.45	25													33
34	-19.37	19.00	10.00		黄灰	細 砂	17.00m付近粘土ポケット状に混入。 18.10m付近粘土薄く層状に挟む。		18.15	60	29	31										34
35								18.40	60													35
36								19.15	19													36
37								19.34	57	15	19	23										37
38								20.15	30													38
39								20.45	60	15	20	25										39
40								21.15	30													40
41								21.45	60	14	23	29										41
42								22.15	29													42
43								22.44	60	18	20	22										43
44								23.15	28													44
45								23.43	55	15	18	22										45
46								24.15	30													46
47								24.45	50	13	16	21										47
48								25.15	30													48
49								25.45	60	30	30											49
50								26.15	19													50
51								26.34	60													51
52								27.15	21	20	32	8										52
53	-28.27	27.90	8.90		暗黄灰	細 砂	27.80m付近貝殻片少量混入。		27.36	15	3	5	7									53
54								28.15	30													54
55								28.45	9	3	3	3										55
56	-29.87	29.50	1.60		黄茶灰	砂混りシルト	酸化物少量点在。		29.15	30												56
57								29.45	20	5	7	8										57
58	-30.82	30.45	0.95		暗黄灰	シルト混り細砂	シルト斑状に混入。		30.15	30												58
59								30.45														59

(N o . 3)

調査地 千葉市稲毛区天台1丁目6番

調査年月日平成9年7月17日～9年7月22日

孔内水位 GL -4.10 m

技術者

標 尺 m	標 高 m	深 度 m	層 厚 m	柱 状 図	色 調	土 質 名	観 察	原 位 置 試 験 深 度 m	標準貫入試験											試料		標 尺 m	
									深 度 m	N 値 回/cm	10cm 毎 の 打 撃 回 数			N 値						採取 方 法	採取 深 度 m		
											10 cm	20 cm	30 cm	0	10	20	30	40	50				60
1	-1.39	0.50	0.50		黒灰	表 土	有機質ローム主体。 粒径は均一。 1.80m付近より粘性は強い。		2.15	3	1	1	1										1
2							2.70m付近より砂分少量混入。		2.50	35	15												2
3							3.20m付近スコリア少量混入。		3.15	4	1	1	2										3
4	-4.79	3.90	3.40		茶褐	ロ ー ム	上部スコリア少量混入。酸化物混入。		3.45	30													4
5							4.10m付近細砂層状に挟む。4.60m付近より粘性は強い。5.60m付近より細砂不規則に混入。		4.15	5	2	2	1										5
6	-6.69	5.80	1.90		乳褐	凝灰質粘土	上部酸化し、黄褐色を呈す粘土多量混入。		4.45	4	1	1	2										6
7							7.00m付近より粒径はやや粗くなり、鉄分凝状に挟む。		5.15	30													7
8							8.30m付近粘土粒状に少量混入。		6.15	54	10	17	27										8
9							9.20m付近薄く層状に酸化している。		6.45	30													9
10							9.50m付近小鉄少量混入。		7.15	60	18	23	19										10
11							10.60m付近粘土分多量混入。		7.43	28													11
12							13.10m付近少し酸化している。		8.15	48	15	16	17										12
13									8.45	30													13
14	-14.79	13.90	8.10		暗黄灰	細 砂	含水量やや多い。シルト不規則に混入。14.50m付近シルト多量混入。		9.15	48	14	14	20										14
15	-15.89	15.00	1.10		暗黄灰	シルト混り細砂	15.00m付近粒径はやや粗く、含水量中位。		10.45	51	14	17	20										15
16							16.00m付近粒径は細かく、シルト不規則に混入。		10.15	30													16
17							17.00m付近鉄分少量混入。		11.15	60	10	17	33										17
18							18.30m付近酸化している。		12.15	60	20	25	15										18
19							19.00m付近粒径は細かい。		12.39	24													19
20							21.00m付近粒径はやや粗い。		13.15	52	12	19	26										20
21									13.45	30													21
22									14.15	59	13	17	29										22
23									14.45	30													23
24									15.15	60	21	26	13										24
25									15.40	25													25
26									16.15	45	10	15	29										26
27									16.45	30													27
28									17.15	60	32	28											28
29									17.32	17													29
30									18.15	60	60												30
31									18.25	10													31
									18.45	60	27	33											
									19.15	60	18												
									19.33	60													
									20.15	60	60												
									20.23	8													
									21.15	60	46	12											
									21.28	12													
									22.15	60	42	18											
									22.29	14													
									23.15	60	60												
									23.25	10													
									24.15	60	41	19											
									24.30	15													
									25.15	60	40	20											
									25.33	18													
									26.15	60	49	11											
									26.28	13													
									27.15	60	60												
									27.25	10													
									28.15	15	4	5	6										
									28.45	30													
									29.15	21	6	7	8										
									29.45	30													
									30.15	60	60												
									30.24	9													

(N o . 4)

調査地 千葉市稲毛区天台1丁目6番

調査年月日平成9年7月23日～9年7月25日

孔内水位 GL -4.00 m

技術者

[illegible]